AnyTone D578UV Mobile Radio
Base Band Update Instruction

UNINSTALL AND REMOVE ALL OLD VERSIONS OF THE SCT_PORT.EXE PROGRAM BEFORE DOING THIS UPDATE – ONLY USE THE LASTEST INSTALL PROGRAM

1. Press and Hold both the PUSH key (Channel Knob Push) and MENU key, and TURN ON THE RADIO and the screen will show "WARNING Boot Mode for Sct!!!"

2. Use the USB cable to connect radio and your PC

3. Run the **most current SetupSCT_Port. msi**

The file is provided in this update in the Install Base Band folder

IMPORTANT NOTE

If an error message appears indicting you need to install Net Framework 2.0 you will have to use the following link to install Net Framework 3.5 which is the update that will have the needed install files to continue:

https://www.microsoft.com/en-US/download/details.aspx?id=21

4. Run SCT_PORT Host Controller by Double Clicking on the Icon on your Desktop.



AnyTone D578UV Mobile Radio
Base Band Update Instruction

5. Follow the screen guides below to set the SCT_Port Host Controller to update the Base Band:





AnyTone D578UV Mobile Radio
Base Band Update Instruction





AnyTone D578UV Mobile Radio
Base Band Update Instruction







With the radio still turned on and the programming cable attached.

Click on Init Port to verify Com Port is active

Message Will Show = “Init Port Successful !!”

AnyTone D578UV Mobile Radio
Base Band Update Instruction





The update is now complete.

Unplug Radio Power Source to reboot radio.

Reapply Power and Turn Radio back on.